

| PART | ART.NR. | 2 CV 4 - 6 | ART.NR. | DYANE | ART.NR. | AZU - AK | ART.NR. | AMI |
|--|--------------------|-------------------|----------------|--------------|----------------|-----------------|----------------|------------|
| LOWER SIDE PANEL RIGHT LEFT | CV001A CV001B | 40.- | D001A D001B | 40.- | F001A F001B | 29.- | A001A A001B | 27.- |
| FLOOR PANEL RIGHT LEFT | CV002A CV002B | 40.- | D002A D002B | 40.- | F002A F002B | 29.- | A002A A002B | 45.- |
| FLOOR PANEL UNDER PEDALS (REPAIR SECTION) | CV003 | 39.- | D003 | 40.- | F003 | 39.- | / | |
| A AND C POST | / | | D004 | 15.- | / | | / | |
| BOX PANEL (COMPLET) | CV005 | 73.- | D005 | 73.- | / | | / | |
| TRUNK COMPARTMENT(COMPLET) | CV006 | 67.- | D006 | 67.- | / | | / | |
| A PANEL RIGHT LEFT | CV007A CV007B | 18.- | / | | F007A F007B | 18.- | / | |
| REAR PANEL (REPAIR SECTION) | CV008 | 23.- | D008 | 23.- | / | | / | |
| FIREWALL (UNDER FRONT BONNET) | CV009 | 27.- | / | | F009 | 27.- | / | |
| PANEL UNDER TRUNK COMPARTMENT | / | | / | | / | | A010 | 23.- |
| 1. PANEL (BEHIND SEATS) | / | | / | | F011 | 44.- | / | |
| 2. PANEL (UNDER TRUNK) | / | | / | | F012 | 44.- | / | |
| 3. PANEL (UNDER TRUNK) | / | | / | | F013 | 35.- | / | |
| REAR PANEL (WITHOUT REAR BUMPER) | / | | / | | F014 | 52.- | / | |
| REAR PANEL (REPAIR SECTION) | / | | / | | F015 | 14.- | / | |
| REAR PANEL | / | | / | | F016 | 27.- | / | |
| SIDE PANEL | / | | / | | F018 | 23.- | / | |
| TRUNK COMPARTMENT | / | | / | | F019 | 44.- | / | |
| INNER WING,REAR RIGHT LEFT | / | | / | | F020A F020B | 48.- | / | |
| REAR TRUNK REAR TRUNK WITH DOOR | CVPP001 CVPP002 | 53.- 130.- | | | | | | |



ANISO d.o.o.Ulica Luke Kruniča 33, 2204 Miklavž
P.E. FRAM 43 A
SLOVENIA

PH 00386(0)2 601 2010
FAX 00386(0)2 601 2009
MOBILE 00386(0)70 360 045